



## GALVANIC CORROSION:

	Cuivre	Laiton	Acier Cuivré	Acier Inox 304	Acier Inox 316	Acier	Acier Galvanisé	Aluminium	Zinc
Cuivre	😊	😊	😊	😊	😊	😞	😞	😞	😞
Laiton	😊	😊	😊	😐	😊	😞	😞	😞	😞
Acier Cuivré	😊	😊	😊	😐	😊	😞	😞	😞	😞
Acier Inox 304	😐	😐	😐	😊	😊	😐	😞	😐	😞
Acier Inox 316	😊	😊	😊	😊	😊	😊	😞	😞	😞
Acier	😞	😞	😞	😐	😊	😊	😊	😊	😊
Acier Galvanisé	😞	😞	😞	😐	😐	😊	😊	😊	😊
Aluminium	😞	😞	😞	😐	😞	😊	😊	😊	😊
Zinc	😞	😞	😞	😞	😞	😊	😊	😊	😊



Very low corrosion potential



Low corrosion potential



High corrosion potential

## THERE ARE SEVERAL DIFFERENT TYPES OF CORROSION:



**Corrosion by pitting** (all stainless steel grades can be affected by this)

Causes (examples of factors that can cause or increase the risk of this type of corrosion):

- extended contact with saline solution if your stainless steel has a low chrome-content (this type of stainless steel is not suitable for this usage as it is not resistant enough for such an aggressive product)
- cleaning product stagnation or permanent presence of chlorides (inadequate rinsing)
- poor quality welding (e.g. too much residual oxygen during the welding process) or welding which has not been stripped/passivated
- iron contamination (e.g. iron particles embedded in the material during its manufacture etc.)
- welding which has not been followed by a decontamination or passivation process



**Crevice corrosion** (all stainless steel grades can be affected by this)

Causes (examples of factors that can cause or increase the risk of this type of corrosion):

- confined areas (e.g. gaps, areas under gaskets, clamps etc.) which make it harder to carry out passivation processes
- deposit build up (e.g. limescale, dirt etc.) which make it harder to carry out passivation processes



**Stress corrosion** (only for austenitic stainless steel)

3 trigger factors (when cumulated):

Tensile stresses\* in the stainless steel + the presence of chlorides\*\* + temperature >60°C\*\*\*

\*If tensile stresses in the austenitic stainless steel exceed 20% of its yield strength, the risk of stress corrosion is high. If tensile stresses are greater than 50% of its yield strength, the risk is very high or this could even lead to pervasive corrosion etc.

\*\*This can be triggered by tap water (with the presence of 30 to 60ppm chlorides).

\*\*\*The higher the temperature, the quicker corrosion will take place.



**Corrosion by erosion** (all stainless steel grades can be affected by this)

Example: the mechanical wear of a pipe's passivation layer due to fluid cavitation etc.



**Intergranular corrosion** (all stainless steel grades can be affected by this)

This type of corrosion can occur in heat-affected zones (on machine-welded structures). The high heat that is applied to steel during the welding process can modify an alloy's molecular characteristics and, as a consequence, change its properties.

## HOW TO PREVENT CORROSION

**During the design phase you should:** choose your material according to your process's risks (e.g. chlorides, temperature etc.); choose your components' shapes and assembly techniques so that you favour fluid flow, avoid creating retention zones, limit material stresses and confinement zones etc.

**During manufacture you should:** preserve the material's surface condition (e.g. surface finish, make sure there is no iron contamination etc.); limit stresses; carry out decontamination, stripping and passivation processes; carry out electrolytic polishing etc.

**During use you should:** limit the period of time that surfaces are in contact with aggressive products; keep surfaces in a good state of cleanliness (but be careful to minimise cleaning time length and the concentration of cleaning products that are applied to the surfaces); make sure you rinse all cleaning products from the surface carefully after cleaning.